

D&D Facility Characterization Interview Checklist

ID No.: 771C

Date: 10/09/00

Page 1 of 2

Check List for - Title: D&D Facili	ty Characterization - Interviews
------------------------------------	----------------------------------

CRITERIA: A D&D Characterization Protocol, RFETS MAN-077-DDCP, Rev. 0

A Facility Disposition Program Manual, RFETS MAN-076-FDPM

Λ RFETS Radiological Safety Practices, January 12, 1998

Facility Name & Type (1, 2, or 3) Building 771C, Type 2 Facility Drum Storage and Counting	
Personnel Interviewed (Name & Title/Function) Don L. Cox, Mechanical Engineer V, D&D Closure	
	Y/ N
Does a current WSRIC exist for the facility?	Υ
If so, are there exceptions to the WSRIC as written?	
COMMENTS (incl. WSRIC contacts)	
WSRIC Contact is James M. Schoen who is in charge of the WSRIC Reports, T130J, X3579, C-83	3
Are rad surveys available that indicate current status of the facility?	<u>N</u>
Are historical rad surveys available that indicate historical status, or evolution, of the facility?	Y
COMMENTS N* According to Sarah J. Roberts, X3008, ARCDA, T771Q, any historical data, which	ı is
probably at the Federal Center, would not be adequate for unrestricted release (i.e. Pre-Demolition S	urvey
or Property release Evaluation). New monitor surveys would have to be taken.	
Is an HRR available for the facility?	Y
Do any other reports exist beyond the HRR (e.g., spill reports, reportable incidents, etc.) that further	
Characterize the facility relative to chemical &/or radiological contamination?	
Are engineering drawings (esp. "as-builts") available?	
Are any nonconformances or issues with the facility status currently being tracked in PATS?	<u>N</u>
If so, what are the issues (note in Comments, below)?	
COMMENTS The building does sit on UBC 771. The Plant quit using lead based paint in the 1980's	<u>, if</u>
this facility was painted prior to this time lead based paints may have been used.	
Have any types of chemical characterization, incl. asbestos, been performed recently?	<u>N*</u>
If so, what types of characterization were performed (note in Comments, below)?	
COMMENTS N* No asbestos characterization data exists for Building 771C, Drum Storage and Cou	
according to Bret Clausen X7781, Building 130, Room C-252. The asbestos data reports are located	
Cubicle 273 of building 130 and the reports are under the control of Bret Clausen with Rae Eklund a	<u>is</u>
backup contact for the asbestos reports.	
Interviewed by: D. A. Burton / 10/09/00	
Print Name Signature Interview Date	
First Name Signature: Interview Date	
A	
•	

1/2

RECEIVED RECORDS CENTER

AUMIN RECCRD



D&D Facility Characterization Interview Checklist

ID No.: <u>771C</u>

Date: 10/09/00

Page 2 of 2

What timeframe did the interviewee work in the facility? 1974 to 2000
Has the building configuration changed since you worked in the building? If so, in what way? No.
What types of equipment were in the building during the interviewee's time there? Equipment for in the floor and above the floor counting of waste drums to determine the amount of SSN material in the drum.
Where was the equipment located? (specific rooms/areas) In the building.
Were any radioactive materials or metals handled in the building? If so, what types? Yes. Contaminated waste contained waste drums.
Which equipment handled radioactive material? Hand trucks.
Were any chemicals handled in the building? If so, what types? No
Did any spills or uncontrolled releases of radioactive materials or chemicals occur while you were working in the facility? No
Were these spills/releases cleaned-up? <u>N/A</u>
Where did these spills/releases occur? N/A
Interviewed by: D. A. Burton / Definition / 10/09/00 Print Name Signature Interview Date

